



Application Note

July 15, 1948

ERRATUM NOTICE

for

Application Note AN-133 "Improved Arrangement of Base-Pin Connections in
New Miniature Tube Types".

Paragraph 4 page 2 discusses the possibilities of shock hazard in an ac/dc receiver circuit utilizing one diode section of a 12AT6 for gas-gate purposes should a 35C5 or 50C5 be accidentally inserted into the socket of the 12AT6. The solution described, however, neglects the possibilities of shock hazard resulting from the insertion of a 35W4 rectifier into the 12AT6 socket. When such possibilities of shock hazard exist, it is advisable to eliminate the gas-gate diode.

Please file this erratum notice with your copy of Application Note AN-133 and mark the indicated paragraph accordingly.